Non-rodent USDA specific techniques and regulations for users of these species (ie rabbits, ferrets, swine)	
One Person Batch Technique:	
 Resetting of the sterile surgical work area between animals and establishing a new sterile field for the next patier removal of completed animal from station, cleaning of all instruments, then "return to the initial set up Following surgical wound closure, anesthesia turned off, vaporizer setting "0" only oxygen delivered, and patie monitored by the surgeon Instruments cleaned grossly (e.g., blood removed) and placed in "dirty" saline or water bowl Place groups of 4-6 instruments 	